

## SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

>5 ppm

EFFECTS OF OVEREXPOSURE

**DANGER!** Toxic if absorbed through skin. Causes severe skin and eye burns. May cause sensitization and other allergic responses.

EMERGENCY AND FIRST AID PROCEDURES

If contact occurs, wash skin immediately with soap and water. Flush eyes immediately with water for 15 minutes. Get medical attention.

## SECTION VI - REACTIVITY DATA

<b>STABILITY</b>	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	
<b>INCOMPATIBILITY (Materials to avoid)</b> Acids and strong oxidizing agents			
<b>HAZARDOUS DECOMPOSITION PRODUCTS</b> Nitrogen Oxides, CO and/or CO <sub>2</sub>			
<b>HAZARDOUS POLYMERIZATION</b>	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	Will exotherm when combined with Part A

## SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Flush away spilled material with

large volumes of water

WASTE DISPOSAL METHOD

Landfill or controlled burning as regulated by all governmental agencies.

## SECTION VIII - SPECIAL PROTECTION INFORMATION

<b>RESPIRATORY PROTECTION (Specify type)</b> Air-supplied mask		
<b>VENTILATION</b>	LOCAL EXHAUST Preferred	SPECIAL
	MECHANICAL (General)	OTHER
<b>PROTECTIVE GLOVES</b> Plastic		<b>EYE PROTECTION</b> Goggles
<b>OTHER PROTECTIVE EQUIPMENT</b> Face shield, rubber apron, eye bath and safety shower.		

## SECTION IX - SPECIAL PRECAUTIONS

<b>PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING</b>	Avoid contact with skin or clothing.
<b>OTHER PRECAUTIONS</b>	
ANSI Classification 4&5	